



THERMITE BRAZE

NOTES:

1. CLEAN PIPE TO BRIGHT METAL.
2. THERMITE BRAZE TO BE CADWELL BY ERICO PRODUCTS OR EQUAL.
3. USE PROPER BRAZE ALLOY FOR STEEL.
4. TEST BRAZE BY PULLING ON WIRE AND STRIKING BRAZE.
5. COAT BRAZE WITH ROYSTON PRIMER AND "HANDY CAP".

SPECIAL NOTE:

THERMITE BRAZE KIT SUPPLIED BY FARWEST CORROSION CONTROL
GARDENA, CA. (214) 770-6425.

JURUPA COMMUNITY SERVICES DISTRICT

SCALE: NONE		THERMITE BRAZE DETAIL	DRAWING NO.
DATE: SEPTEMBER 2020			K-4
REV.	APPROVED BY: <i>Sinnaro Yos</i>	ALBERT A. WEBB ASSOCIATES CONSULTING ENGINEERS	
	Sinnaro Yos, P.E. C68607	RIVERSIDE CALIFORNIA	W.O. 19-0248